

Raportul istoricului vehiculului pentru VIN# JM1DKBC77G0102194



2016 Mazda CX-3

ID raport: **OCAAB988**

Data generată: **5 dec 2025**

Conținutul raportului poate fi actualizat substanțial după data generării. La dorință puteți să rulați din nou un raport pentru a obține date cât mai actualizate despre vehicul.



















Tip de utilizare: **Personal**

 Specificațiile vehiculului Înregistrări găsite	 Detalii kilometraj 74,080 M	 Fotografii cu vehicule Numărul total de 20 fotografii	 Înscriere în talonul de înmatriculare 11 înregistrări găsite	 Rechemări 3 înregistrări găsite
 Istoricul vânzărilor 2 înregistrări găsite	 Accident și daune 1 înregistrări găsite	 Gaj și confiscare 0 Înregistrări găsite	 Înregistrarea deturnărilor 0 Înregistrări găsite	 Istoricul serviciului 0 Înregistrări găsite

Specificațiile vehiculului

VIN:	JM1DKBC77G0102194	face:	Mazda
Stil:	4D SUV AWD	Trim:	Touring FWD
Transmisie:	6-Speed Automatic	Tractiune:	Front Wheel Drive
Tip Carburant:	Gas	Garda la Sol:	-
Sistem anti-frânare:	4-Wheel ABS	Scaune standard:	5

	Înălțime totală:	60.70 in.		Lățime totală:	69.60 in.
	Kilometraj autostradă:	35 miles/gallon		An:	2016
	Model:	CX-3		Fabricat în:	JAPAN
	Motor:	2.0L L4 DOHC 16V		Cilindri:	4
	Tipul de direcție:	R&P		Dimensiunea rezervorului:	12.70 gallon
	Anvelope:	215/60R16		Sistem Antifurt:	-
	Locuri opționale:	-		Lungime totală:	168.30 in.
	GVWR:	-		Kilometrajul orașului:	29 miles/gallon

Istoricul vânzărilor

DATA	VÂNZĂTOR	EVENIMENT	PREȚ
13 iul 2022	Platformă de listare	Scos la vânzare de către dealer	-
24 oct 2024	Câștigă licitația	Pus la vânzare	\$14,598

Detalii kilometraj

DATA	KILOMETRAJ	SURSĂ DE DATE
8 oct 2015	6 M	MOTOR VEHICLE DEPARTMENT
25 iul 2022	74,080 M	MOTOR VEHICLE DEPARTMENT

Istoric al cărții de identitate a vehiculului (CIV)

Adunăm toate informațiile posibile despre titlul vehiculului, dar este posibil ca raportul să nu includă unele înregistrări ale titlului din cauza reglementărilor canadiene privind divulgarea datelor.

DATA	LOCAȚIA	DETALII
8 oct 2015	MANITOBA	CANADIAN REGISTRATION ISSUED OR RENEWED
30 sep 2016	MANITOBA	CANADIAN REGISTRATION ISSUED OR RENEWED


30 sep 2017	MANITOBA	CANADIAN REGISTRATION ISSUED OR RENEWED
30 sep 2018	MANITOBA	CANADIAN REGISTRATION ISSUED OR RENEWED
29 mai 2019	ENFIELD, NS	CANADIAN REGISTRATION ISSUED OR RENEWED
14 aug 2020	NOVA SCOTIA	CANADIAN REGISTRATION ISSUED OR RENEWED
1 sep 2021	NOVA SCOTIA	CANADIAN REGISTRATION ISSUED OR RENEWED
25 iul 2022	QUEBEC	ODOMETER READING FROM CANADIAN PROVINCE CANADIAN REGISTRATION ISSUED OR RENEWED
26 iul 2022	QUEBEC	CANADIAN REGISTRATION ISSUED OR RENEWED
31 aug 2023	QUEBEC	CANADIAN REGISTRATION ISSUED OR RENEWED
31 aug 2024	QUEBEC	CANADIAN REGISTRATION ISSUED OR RENEWED

Istoricul serviciului

 0 Înregistrări găsite

Accident și daune

Nu toate evenimentele legate de daune sunt raportate în prezent către ClearVin, raportul poate să nu conțină daune minore și zgârieturi sau probleme nedocumentate ale vehiculului. Vă recomandăm cu căldură să faceți o inspecție independentă a vehiculului pentru a vă asigura că vehiculul nu are daune ascunse înainte de a lua decizia de a cumpăra un vehicul.



Data:	24 oct 2024
Deteriora:	⚠️ SIDE ⚠️ PARTEA FRONTALĂ
Airbag-uri:	INTACT
Costuri est. de reparație:	\$16,627

Gaj și confiscare

Informații sechestru	✓ Fără probleme raportate
Deschideți gaj	✓ Fără probleme raportate
Date istorice privind cauțiunea	✓ Fără probleme raportate

Înregistrarea deturnărilor

NU ESTE LISTAT CA FURAT



✓ Nu au fost găsite înregistrări de furt pentru numărul tău VIN

Marcaje în cartea de identitate a vehiculului

FĂRĂ MĂRCI



CATEGORIA BRAND

STAREA

Export

✓ Fără înregistrări

Utilizare inchiriere	✓ Fără înregistrări
Folosirea poliției	✓ Fără înregistrări
Declanșare airbag	✓ Fără înregistrări
Accidente grave	✓ Fără înregistrări
Informații de salvare	✓ Fără înregistrări
Furt/Deținerea	✓ Fără înregistrări
Daune provocate de inundații	✓ Fără înregistrări

Detalii privind vânzările anterioare

COPART

PUNE LA VANZARE 24 oct 2024

Vânzător:	-	Data vânzării:	21 ian 2025
Locația:	QC - Montreal	Daune primare:	SIDE
Tipul documentului:	QC POUR PIECE SEULEMENT	Daune secundare:	partea frontală
Stare vânzare:	Pure Sale	condiție:	RUN & DRIVE VERIFIED
ACV:	\$14,598	Kilometraj:	-















MFD. BY MAZDA MOTOR CORPORATION

DATE 05/15

FRONT GAUR/PNBE AU 2112 LB 958 KG

WITH/AVEC

TIRES/PNEUS

RIMS/JANTES

COLD/A FROID

X

KPA/ PSI

GUWR/PNBU 3990 LB 1810 KG

REAR GAUR/PNBE AR 1896 LB 860 KG

WITH/AVEC

TIRES/PNEUS

RIMS/JANTES

COLD/A FROID

X

K PSI

VIN: JM1DBCT7G0102194 TYPE:PC/VT



COLOR CODE 41U MADE IN JAPAN

Platformă de listare

PUNE LA VANZARE 13 iul 2022

Vânzător:

Oto Crmazie Data vânzării:

10 aug 2022

Locația:

Montreal, QC, H1Z 2G8

condiție:

used

Preț:

- kilometraj:

-











Rechemări

DATA REVOCARII	RETRAGERE NR.	COMPONENTĂ (COMPONENTE)
11 apr 2016	16V203000	STEERING

KEY 'REPORT.SUMMARY (RO)' RETURNED AN OBJECT INSTEAD OF STRING.

Mazda North American Operations (Mazda) is recalling certain model year 2016 CX-3 vehicles manufactured June 1, 2015, to December 2, 2015, 2013-2014 Mazda2 vehicles manufactured July 3, 2013, to August 8, 2014, 2014-2016 CX-5 vehicles manufactured January 19, 2013, to December 2, 2015, and 2013-2015 CX-9 vehicles manufactured December 6, 2012, to July 31, 2015. The lower mounting nuts and bolts that attach the front strut assembly to the steering knuckle may loosen, allowing the steering knuckle to separate.

CONSECINȚĂ

-

REMEDIU

Mazda will notify owners, and dealers will inspect the lower mounting nuts and bolts that secure the front strut assembly to the steering knuckle. If the bolts are loose, they will be replaced and then correctly tightened, free of charge. The recall is expected to begin May 20, 2016. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 9316D.

NOTE

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

DATA REVOCARII	RETRAGERE NR.	COMPONENTĂ (COMPONENTE)
6 sep 2016	16V644000	STRUCTURE:BODY:HATCHBACK/LIFTG ATE

KEY 'REPORT.SUMMARY (RO)' RETURNED AN OBJECT INSTEAD OF STRING.

Mazda North American Operations (Mazda) is recalling certain model year 2010-2013 Mazda3 and Mazdaspeed3 vehicles manufactured November 18, 2008, to June 8, 2013, 2012-2015 Mazda5 vehicles manufactured October 26, 2010, to June 22, 2015, 2016 CX-3 vehicles manufactured June 1, 2015, to December 26, 2015, and 2013-2016 CX-5 vehicles manufactured December 15, 2011, to December 26, 2015. On the affected vehicles, the lift gate support struts may corrode, possibly causing the struts to break and/or the lift gate to drop unexpectedly.

CONSECINȚĂ

-

REMEDIU

Mazda dealers will replace the both lift gate supports, free of charge, however parts are not currently available. The recall began April 2017. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 9916H.

NOTE

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

DATA REVOCARII	RETRAGERE NR.	COMPONENTĂ (COMPONENTE)
14 iul 2023	23V487000	BACK OVER PREVENTION: SENSING SYSTEM: CAMERA

KEY 'REPORT.SUMMARY (RO)' RETURNED AN OBJECT INSTEAD OF STRING.

Mazda North American Operations (Mazda) is recalling certain 2014-2018 Mazda3 and 2016-2021 CX-3 vehicles. The rearview camera image may not display properly by showing a flickering or distorted image.

CONSECINȚĂ

-

REMEDIU

Dealers will inspect and replace the rearview camera, as necessary. In addition, dealers will install a wiring harness fastening seal. All repairs will be performed free of charge. Interim notification letters, notifying owners of the safety risk, were mailed September 13, 2023. A second notice will be sent once the final remedy is available. Owners may contact Mazda customer service at 1-800-222-5500 Option 6. Mazda's number for this recall is 6023G.

NOTE

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.